





L- 1200 mm

L-1400 mm

L-1600 mm

L-1800 mm



X4



X10




X2




X2



X18



X4



X2

L- 1800 mm



X6



X6




X8

L- 1200 mm


L-1400 mm

L-1600 mm


L-1800 mm




X2




X4



X2




X2




X2

L- 1800 mm




M8x20


X2




L- 1200 mm
X2




L- 1400 mm
X2



L- 1600 mm
X2




L- 1800 mm
X2









M8x16

X6










Užveržimo momentas
neturi viršyti maks. 10 Nm
The thrust moment must
not exceed max. 10 Nm







ARBA/OR






*Išreguliuotą stalą įjungiame
į elektros tinklą*

*Turn the table around to standing
position and plug the cable in*





DĖMESIO!

Prieš pirmą stalo naudojimą ir kiekvieną kartą, kai stalas bus iš naujo įjungtas į elektros tinklą, reikės atlikti šiuos veiksmus:

- 1. Spauskite mygtuką "žemyn", kol stalas bus visiškai nuleistas. Laikykite nuspaustą mygtuką tol, kol stalas nejudės.*
- 2. Dabar stalą galima pakelti aukštyn.*

ATTENTION!

Before using the table for the first time and each time the table is reconnected to the power socket, the following steps will be required:

- 1. Press the "down" key until the desk is lowered completely. Hold the key until the desk no longer moves.*
- 2. Reactivate the down key and hold until the desk no longer moves. Now the desk can be raised.*

